Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: BENZ 14-21H

Field Name: BAILEY Well File #: 16327

Date Incident: 4/15/2016 Time Incident: 11:42 Facility ID Number:

County: DUNN Twp: 146 Rng: 94 Sec: 21 Qtr:

Location Description:

Submitted By: Bryan Gallegos Received By:

Contact Person: Bryan Gallegos

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

6.08

barrels

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/26/2016 Clean Up Concluded: 4/15/2016

Risk Evaluation:

Immediate risk was minimal because spill was contained on location,

Areal Extent:

Potential Environmental Impacts:

All personnel stayed clear of fluid. Personnel built berms around the fluid to keep it from moving off location.

Action Taken or Planned:

Personnel on location immediately built berms around fluid to keep it from moving and vac truck removed fluid from ground. Contaminated soil removed and placed in remedial pile.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/18/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC retains oversight.